



ENGINEERING

# Technical Bulletin

**INDEX**

Sheet: 1 of 2

5000 Bodymaker

Issue: 06. 07. 09

**Technical Bulletin and TB Number:-**

**Category of TB:-**

Coolant Flow Switches <b>TB5000-001</b>	Recommended
Swing Lever Hose Kit <b>TB5000-002</b>	Maintenance
Secondary Oil Filtration <b>TB5000-003</b>	Maintenance
Oil Level Float Switch to Sensor Conversion <b>TB5000-005</b>	Maintenance
Double Pump Conversion <b>TB5000-007</b>	Maintenance
New Rear Hold Down Link Assy. <b>TB5000-008</b>	Maintenance
New Rotary Union Unit. <b>TB5000-009</b>	Maintenance
Low Pressure Primary Filtration <b>TB5000-010</b>	Maintenance
Crankshaft Main Brg. & Main Brg. Lubrication <b>TB5000-011</b>	Maintenance
Water Absorption Filter <b>TB5000-014</b>	Recommended
Improved Hydraulic Clutch and Brake, Life & Performance <b>TB5000-015</b>	Maintenance
Sealing Upgrade for Hyd. Clutch & Brake <b>TB5000-018</b>	Maintenance
Improved Rear Hold Down Link Assembly <b>TB5000-023</b>	Maintenance
Dome Station Setting Procedure <b>TB5000-024</b>	Factory Implementation
Conversion to One Piece all Aluminium "Padless" Yoke Slide Assy. <b>TB5000-025</b>	Overhaul
Leader Pin Hold Down Mechanism <b>TB5000-026</b>	Recommended
Microdome Dome Station <b>TB5000-027</b>	Recommended
Topwall Variation Reduction Package <b>TB5000-028</b>	Recommended
Improved Rotary Cup Feed <b>TB5000-029</b>	Recommended
Securing of Swing Lever Top Sleeve <b>TB5000-032</b>	Recommended
Primary Connecting Rod Cap Retention <b>TB5000-033</b>	Mandatory
Yoke Slide Pin Retention <b>TB5000-036</b>	Recommended
Electronic Dome Overtravel Gauge and Ram Alignment Fixture. <b>TB5000-039</b>	Factory Implementation
Flywheel Assembly Drive Coupling Bushes <b>TB5000-040</b>	Overhaul

Adrian Long,  
CarnaudMetalbox Engineering Plc,  
Dockfield Road, Shipley,  
West Yorkshire, BD17 7AY, UK  
Tel: +44 1274 846208, Fax: +44 1274 846201  
email: adrian.long@eur.crowncork.com

Paul J Orsino III,  
CarnaudMetalbox Engineering Plc,  
79 Rockland Road, Norwalk,  
Connecticut 06854, USA  
Tel: +1 203 853 7325, Fax: + 1 203 866 7627  
email: porsino@crowncork.com



ENGINEERING

# Technical Bulletin

**INDEX**

Sheet: 2 of 2

5000 Bodymaker

Issue: 06. 07. 09

Leader Pin Front Hold Down Assembly - Guide Pod Bushes <b>TB5000-041</b>	Maintenance
Upgrade of Ortlinghaus Clutch & Brake <b>TB5000-042</b>	Recommended
Rear Hold Down Rear Air Bag Monitoring System <b>TB5000-043</b>	Recommended
Composite One Piece Primary & Secondary Ram Bushing Arrangement <b>TB5000-044</b>	Overhaul
Improved Control of Scavenging Pump <b>TB5000-045</b>	Overhaul
Crankcase Lubricant <b>TB5000-046</b>	Factory Implementation
Roller Bearing Type Cam Followers <b>TB5000-047</b>	Maintenance
<i>Unallocated</i> <b>TB5000-048</b>	
Composite Front Bushing Assemblies <b>TB5000-049</b>	Factory Implementation
Secondary Connecting Rod <b>TB5000-050</b>	Recommended
Lightweight Ram <b>TB5000-051</b>	Recommended
Clamping Cover Clamping Assembly <b>TB5000-052</b>	Recommended
Rotary Cup Feed Change Parts <b>TB5000-053</b>	Recommended
Coolant Solenoid Valve <b>TB5000-054</b>	Recommended
IFM Pressure Switch Lubrication Upgrade <b>TB5000-055</b>	Recommended
Rear Air Bag Support Mechanism <b>TB5000-056</b>	Recommended

Adrian Long,  
CarnaudMetalbox Engineering Plc,  
Dockfield Road, Shipley,  
West Yorkshire, BD17 7AY, UK  
Tel: +44 1274 846208, Fax: +44 1274 846201  
email: adrian.long@eur.crowncork.com

Paul J Orsino III,  
CarnaudMetalbox Engineering Plc,  
79 Rockland Road, Norwalk,  
Connecticut 06854, USA  
Tel: +1 203 853 7325, Fax: + 1 203 866 7627  
email: porsino@crowncork.com